




Good practices when using the Winnow system


Make sure the scale feet are firm & even



Keep the area around the scale clear





with no other objects around interfering



Don't overly wet the floor when cleaning it



Never place more than one container on the scale



Place the scale within the marked area

The scale should not go beyond the marked area

