


How to avoid uncategorized transactions on the scale

Scale care

To ensure you have good data in your reports please avoid the following:



No non-food or packaged items

Anything that isn't food eg. plastic, paper, bin bags etc should not be placed on top of the scale.

Avoid stepping on the scale.

The Winnow scale is only used to record food waste, avoid stepping on top of the scale to prevent damage.

Avoid heavy equipment next to the scale.

The scale is sensitive to any weight placed on it, it can trigger an uncategorized transaction if there is any heavy equipment placed next to the scale or if the equipment is touching the scale.